

ROSPA report 2024 -

Works officers action Plan.

Risk levels- **LOW** **MEDIUM** **HIGH**

CHESSBROOK GREEN



WORK REQUIRED	RISK LEVEL	DATE COMPLETED
Swing basket, re-glue & fill gaps & joints as necessary.	Medium	
Balance trail- logs loose in ground, to be reset.	Medium	
Agility ladder-Consult with manufacturer for guidance re suitable maintenance	Medium	
NOTES-		

HENFIELD SKATE PARK



WORK REQUIRED	RISK LEVEL	DATE COMPLETED
General surface is uneven, shallow holes now forming-Make good	Medium	
Access-ground erosion present on grass path from Youth club to skate park	Medium	
Free form street course, replace missing cap from end of rail	High	
Basketball post-item is bent	Medium	
Surface area is cracking- monitor & repair as required	Medium	
Gap between plates exceeds 5mm- repair	Medium	
NOTES-		

KINGSFIELD PLAY AREA




WORK REQUIRED	RISK LEVEL	DATE COMPLETED
Swing, junior, seat bolt loose, vertical support – Check for cracks, consult Wicksteed for advice, replace parts and repair.	Medium	
Trampoline, trip points on surface- Make level	Medium	
Carousel whirl, projecting bolt head-Cut off & file or use correct length bolt	Medium	
Runway, wear in the bushes-remove shackle bolt & check bush & shackle pin wear, replace if necessary	Medium	
NOTES-		

ROTHERY FIELD



WORK REQUIRED	RISK LEVEL	DATE COMPLETED
Pathways, trip points on surface- remove trip points	Medium	
Paving pathway has holes in it- repair	Medium	
Trip point near inspection cover & gate- remove trip points	Medium	
NOTES-		

WANTLEY HILL ESTATE



WORK REQUIRED	RISK LEVEL	DATE COMPLETED
Trees, overhanging branches-regular arboricultural surveys are completed, remove obstructions & overhanging branches	Medium	
Swing seat damage-not immediate replacement required so monitor, replace when hard material exposed	Medium	
Swing, some chain wear- Monitor for further deterioration and replace before 40% wear.	Medium	
Swing shackles, bushes and associated connections need servicing -repair	Medium	
NOTES-		